

DIR-615 Firmware Release Notes

Firmware: FW414B04

Hardware: Dx

Date: 2013/10/29

Note:

1. FW version is advanced to v4.14

Problems Resolved:

1. Fixed the UPnP exploit.
2. Fixed the reported issue from Michael Messner

- OS Command Execution:
http://<IP>/tools_vct.xgi
http://<IP>/tools_system.xgi
- Cross-Site Scripting (XSS)
http://<IP>/bsc_wlan.php
http://<IP>/tools_log_setting.php
- Security Misconfiguration
Telnet Service is open with Authentication.
- Sensitive Data Exposure
<http://<IP>IP/DevInfo.txt>
- Cross-Site Request Forgery
http://<IP>/tools_admin.php

Enhancements:

None

Known Issues:

None